



**NUMBER:** 19-003-06

**GROUP:** Steering

**DATE:** August 30, 2006

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.*

**THIS BULLETIN IS BEING PROVIDED IN ADVANCE. DO NOT ORDER PARTS OR PERFORM ANY ACTIONS RELATED TO THIS BULLETIN UNTIL SEPTEMBER 7, 2006.**

**SUBJECT:**

Steering Shimmy

**OVERVIEW:**

This bulletin involves installing a revised steering damper.

**MODELS:**

1997 - 2006 (TJ) Wrangler

**SYMPTOM/CONDITION:**

Steering shimmy may occur after hitting a bump in the road at highway speeds.

**DIAGNOSIS:**

Check tire dynamic balance. Also check for worn or loose steering & suspension components. Repair as necessary. If the shimmy still exists, perform the Repair Procedure.

**PARTS REQUIRED:**

Qty.	Part No.	Description
1	52088959AB	Damper, Steering

**SPECIAL TOOLS/EQUIPMENT REQUIRED:**

C-3894-A	Puller
----------	--------

**REPAIR PROCEDURE:**

1. Use the procedures outlined in the service information of DealerCONNECT/TechCONNECT 19 - Steering>Linkage>Damper>Removal/Installation to install revised steering damper , p/n 52088959AB.

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

Labor Operation No:	Description	Amount
02-15-20-93	Replace Steering Damper	0.3 Hrs.

**FAILURE CODE:**

ZZ	Service Action
----	----------------